Work Orde Wednesday, April	r ID 68465 13, 2011 4:14:54 PM	r						-				Page 1
Revision ID:	D3443-041 Strut Weldment Assembly			Accept					-	Start Stop		
•	1/13/2011 Start Qt	y: 3.00			Cust Item II Customer:	D:						### ### ##############################
:	Process Plan:	1	Date: <u>//-(/-</u> /3 Date:	Tooling: SPC (Y/N):	Da			-		Start Stop		
Sequence ID/ Work Center ID	Operatio Descripti			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejec Qty		eject umber	Insp. Stamp
Draw Nbr	Revision Nbr											
D3443	Rev C											
Large Fab	Large Fab	Memo Weld assem	bly as per dwg D3443	0.00			,	PD	11-04	4.15	· •	3
110 	QC9- Inspe	ct visual per Memo	QS1004- Fusion Welds	0.00				G(11)	0418	3	ı	· ·

120

QC5- Inspect part completeness to step on W/O

Memo

0.00

Quality Control

Quality Control

	•								×.
W/O:			V	ORK ORDER CHANGE	ES	-			
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•							
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA	\:	Date: _	
	R	esolution:	ion:	QA: N/C C	osed:		Date: _		
NCR:			ORK OR	DER NON-CONFORMA	NCE (NCF	R)			
D.4.T.E.	OTED	Description of NC	Description of NC Corrective Action			Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	k Section		Chief Eng	QC Inspector
						·			
		·							
_									
						ja ja			
								1	

Work Order ID 68465

Wednesday, April 13, 2011 4:14:54 PM



Page 2

Item ID:

D3443-041

4/13/2011

Accept

Setup Start

Revision ID:

Start Date:

Strut Weldment Assembly Item Name:

Required Date: 4/20/2011

Start Oty: 3.00 **Req'd Qty: 3.00**

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start

Stop



Date:

SPC (Y/N):

0.00

0.00

Set Up/

Run Hours

Date:

Tool # Plan

Code

Stop

Reject

Qty

Number Stamp

Insp.

Reject

Sequence ID/ Work Center ID

130

Powdercoat Powder Coating

Operation Description

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

M116964

Memo

ال-Mask holes as per dwg D3443 START TIME: 11000~ OVEN TEMPERATURE: 400%

FINISH TIME: (:302)

140

Quality Control

QC3- Inspect Part Finish

Memo

0.00

0.00

Accept

Qty

150

Small Fab

Small Fab

Small Fab

Memo

0.00

Assemble bearing and ball plungers as per dwg D3443 using DT9518

Ensure bearing rotates smoothly

0.00

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		÷					- The state of the					
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes	No DQA		Date: _			
	R	esolution:	Disposit	ion:	QA:	N/C CI	osed:		Date: _			
NCR:			WORK OR	DER NON-CONFORM	IANCE	(NCR)			•		
DATE	STEP	Description of NC			ection B		Verifica	ation	Approval	Approval		
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng)	Sign & Date	Sectio	n C	Chief Eng	QC Inspector		
					ŀ							
		,										
									·			

Work Order ID 68465

Wednesday, April 13, 2011 4:14:54 PM

Page 3

Item ID:

Accept

Setup Start

Stop



Revision ID:

Item Name:

Strut Weldment Assembly

Start Date:

Required Date: 4/20/2011

4/13/2011

QC:

D3443-041

Start Qty: 3.00

Req'd Qty: 3.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

Date:

Date:

Run Start

Stop

Sequence ID/

Work Center ID

160

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/

Run Hours

SPC (Y/N):

0.00

0.00 11/07/20

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Stamp

170

Packaging

Packaging

180

OC

Quality Control

Identify as per dwg & Stock Location:__

Memo

Memo

0.00

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Reject Number

Insp.

	-												
W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date: _					
		solution:	Disposit	ion:	_ QA: N/C Cld	osed:		Date: _	· 				
NCR:		V	WORK OR	DER NON-CONFORM	ANCE (NCR)							
DATE	STEP	Description of NC			tion B	Verifi	cation	Approval	Approval				
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector				
		<u> </u>											
			1 .						1				

Picklist Print

Wednesday, April 13, 2011 4:14:59 PM

Work Order ID: 68465

Parent Item:

D3443-041

Parent Item Name: Strut Weldment Assembly



Start Date: 4/13/2011

Required Date: 4/20/2011

Start Qty: 3.00

Required Qty: 3.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	t Total Qty	Qty Issued	Date Issued	Status
03443-1		Manufactured	No			100	Each	3.0000	1	3 PD .	11-04-	15	
				Location		Loc (Loc Code					
				WA023	58562		3		-	(3)			
03443-5 		Manufactured	No		·	100	Each	4.0000	1	PD,	1.0415	.	
				Location		Loc (<u>)ty</u>	Loc Code					
				WA023	60230		4		-	(5)			
03453-1 		Manufactured	No	·	60230	100	Each	7.0000	1	8D 11	04.15		
		4		Location		Loc (<u>Oty</u>	Loc Code					
					58564 59449		7 1 6		-	(D)	 ,		
03965-4		Manufactured	No			100	Each	7.0000	1	3	u /04] .	19	
Bearing, Spherical				Location		Loc C	<u>Otv</u>	Loc Code		// '			
				ST100	60479		7 7		•				

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
-						-							
						,							
Part No		PAR #:	Fault Cate	gory:	_ NCR: Yes I	No DQA:		_ Date: _					
	Res	colution:	Dispositio	n:	_ QA: N/C Clo	sed:		Date:					
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR))							
DATE	STEP	Description of NC			ion B	Verifica	tion	Approval	Approval				
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector				

Picklist Print

Wednesday, April 13, 2011 4:14:59 PM

Work Order ID: 68465

Parent Item:

D3443-041

Parent Item Name: Strut Weldment Assembly



58711

Start Date: 4/13/2011

Required Date: 4/20/2011

Page 2

Start Qty: 3.00

Required Qty: 3.00

D3966-4-750

Manufactured

No

100

55.0000 Each


PD 11-04.15

Pin, Dowel


Location	Loc Qty	Loc Code
ST100	55	

55


	•						•	
W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHA	INGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-		
	-							
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	1
	Re	esolution:	Dispositio	on:	_ QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	·							
	·							
					`			
						·		
						•		
							·	
								,




W/O:			W	ORK ORDER CHANG	SES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			- A CONTRACTOR OF THE CONTRACT					r tou lvigi		
		·								
Part No	1	PAR #:	Fault Cate	egory:	NCR: Yes	No DQA	•	Date: _		
	R	esolution:	Dispositio	n:	_ QA: N/C C	losed:		Date: _		
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC					
DATE	OTED	Description of NC			tion B	Verifica	ation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section		Chief Eng	QC Inspector	
				•						
					,	٠				
								•	,	



W/O:		WORK ORDER CHANGES											
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector				
								Prod Mgr	ao mopeotor				
		÷											
Part No	•	PAR #:	_ Fault Cat	tegory:	NCR: Yes	No DQ	A:	Date:					
	Resolution:			ion:	QA: N/C Clo	sed:		Date: _					
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NCR)							
		Description of NC		Corrective Action Section		Verific	cation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Chief Eng	QC Inspector				
								,					
					:								
									1				



	•								
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						l			
		·							
Part No	:	PAR #:	Fault Ca	tegory:	_ NCR: Ye	s No DO	QA:	Date: _	
	R	esolution:	Disposit	ion:	_ QA: N/C	Closed: _		Date: _	
NCR:	WORK ORDER NON-CONFORMANCE (NCR)								
DATE	CTED	Description of NC			ion B	Veri	Verification Approx		Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	ι& _{Se} ,	ction C	Chief Eng	QC Inspector
Î									
ŕ									



W/O:			W	ORK ORDER CHANGE	ES			***************************************		
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									•	
		·								
				_				-		
Part No	:	PAR #:	Fault Cat	egory:	NCR: Y	es N	o DQ	A:	_ Date: _	
Resolution:			Dispositi	on:	QA: N/C	Clos	sed:		Date: _	
NCR:			WORK ORE	DER NON-CONFORMA	NCE (N	CR)				
DATE	eten.	Description of NC		Corrective Action Section			Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig D	n & ate	Secti		Chief Eng	QC Inspector
							-:			
				. Exploration		·	-			
1 me 12 4						ž				
										-
									्रोस 	;
						ř			,	
										,